

DRO Digital Readout Function List

D80 LCD DRO

Zeroing, Data Recovery	●
Value Inputting	●
Metric/Imperial Switching	●
Power Off Memory Function	●
Encoder Selection (Rotary or Linear)	●
Resolution Setting	●
Linear Compensation	●
Counting Direction Setting	●
1/2 function (Centering)	●
ABS/INC Coordinate	●
200 sets SDM Coordinates	●
REF	●
Calculator	●
Non-linear Compensation	●
PLD Function	●
PCD Function	●
Simple R Function	●
Smooth R Function	●
Rectangle Chambering Function	●
Taper Measuring Function	●
Bevel Function	●
Radius/Diameter Conversion	●
Axis summing	●
Digital Filtering Function	●
Preview Drawing	●
Dynamic Graphic	●
16 sets of Tool Memory	●
EDM	○
Rotational Speed Measurement	○
RS232 interface	○
Linear Measuring Basing Rotary Encoder	●

Remarks: ● Standard Function ○ Optional Function