

Digital Readout Function List					
	DL50	D50	D100	D60	D80 / D80M
Function \ Model	DL50 1A 2A 3A	D50 1A 2A 3A	D100 D100-2V,D100-3V	D60 D60 2V,D60-3V	D80 / D80M 1-5V
Zeroing,Data Recovery Value Inputting Metric/Imperial Switching Power Off Memory Function Encoder Selection (Rotary or Linear) Resolution Setting Linear Compensation Counting Direction Setting 1/2 function (Centering)	●	●	●	●	●
ABS/INC Coordinate		●			
200 sets SDM Coordinates		●			
REF		●	●	●	●
Calculator		●			
Non-linear Compensation					
PLD Function		●	●	●	●
PCD Function		●	●	●	●
Simple R Function			●	●	●
Smooth R Function			●	●	●
Rectangle Chambering Function					●
Taper Measuring Function			●	●	●
Bevel Function					●
Radius/Diameter Conversion	●	●	●	●	●
Axis summing		●	●	●	●
Digital Filtering Function		●	●	●	●
Preview Drawing					●
Dynamic Graphic					●
16 sets of Tool Menory					●
EDM			○	○	○
Rotational Speed Measurement		○			○
RS232 interface	○	○	○	○	○
Linear Measuring Basing Rotary Encoder		●			●

Remarks: ● Standard Function    ○ Optional Function